

ROSEBURG

LUMBER CO.

P.O. BOX 1088 · ROSEBURG, OREGON 97470 PHONE (503) 679-8741

December 29, 1981

Douglas County Surveyor
Douglas County Court House
Roseburg, OR 97470

Dear Sir:

I have remonumented a bearing tree for section corner of sections 23, 24, 25 and 26 T.29S., R.8W., W.M. as follows:

Found: 1924 Cad. Brass Cap in good condition.
18" Fir N33E 32.3 ft. O.B.T. Good Cond.
18" Fir S15E(record S5E) 35.6 ft. O.B.T. Good Cond.
18" Fir S35W 21.1 ft. O.B.T. Good Cond.
18" Fir N65W 33.7 ft. O.B.T. - Now a stump in a clear cut of the SE corner of Section 23.

Set: 5/8x30" I.R. rebar with aluminum cap marked.
L.S. 498 at base of O.B.T. stump, N65W, 33.3 ft.

Sincerely,

ROSEBURG LUMBER CO.



Howard W. Johnstone
RLS 498

HWJ/clb

cc: Luke Templin
Bureau of Land Management
777 NW Garden Valley Blvd.
Roseburg, OR 97470

