

OCT 1, 1982

FILED
RECEIVED
NOV 15 1982
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

CORNER RENEWAL FOR CLOSING CORNER.

BETWEEN SECTIONS 3 & 4 T24S RBW ON TOWNSHIP LINE.

- FOUND A 20" D. FIR (NOW 26") WHICH BEARS S78°E 36.2 FT (OBT)
- A 36" D. FIR (NOW A STUMP) WHICH BEARS N57°E 36.6 FT. (OBT)
- A 36 D FIR (NOW A STUMP) WHICH BEARS N4°W 30.5 FT. (OBT)

ALSO FOUND A 2" PIPE AND BRASS CAP IN PROPER POSITION MARKED.



A NEW ROAD WAS TO BE CONSTRUCTED NEAR THIS CORNER AND IT APPEARED THAT THE CORNER POSITION COULD BE OBLITERATED, SO I REMOVED THE PIPE & BRASS CAP FROM ITS ORIGINAL POSITION AND REPLACED WITH A 3/8" X 30" IRON ROD SET ONE FOOT BELOW THE SURFACE OF THE NATURAL GROUND LINE. WHEN CONSTRUCTION WAS COMPLETED, I RESET THE PIPE & BRASS CAP IN ITS ORIGINAL POSITION AND ALSO LEFT THE IRON ROD IN PLACE.

MARKED TWO NEW BTS AS FOLLOWS:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

A 37" D. FIR BEARS S23 1/2° E 26.2 FT

MARKED T24S RBW S 3 BT

Burton W. Holt

OREGON
OCTOBER 4, 1937
BURTON W. HOLT
418

A 12" MAPLE BEARS S23°W 38.6 FT

MARKED T24S RBW S 4 BT

OCT 1, 1982 THE NEWLY CONSTRUCTED ROAD BEARS NORTH APPROX. 50 FT AND IS APPROX. 30 FT ABOVE THE CORNER.

#122 T23B ✓
#103 T24B ✓

G. L. File No. 58/229-14
0