

Shaner Engineering, Inc.

PLANNING • SURVEYING • ENGINEERING
P.O. BOX 1430
ROSEBURG, OREGON 97470

FILED
RECEIVED

DEC 29 1981

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.


FOUND QUARTER SECTION CORNER COMMON TO SECTION 34, T26S, R4W, W.M.
AND SECTION 3, T27S, R4W, W.M., DOUGLAS COUNTY, OREGON

For: Joseph A. Barnes
1577 N.W. Evans Avenue
Roseburg, Oregon 97470

By: Shaner Engineering, Inc.
P.O. Box 1430
Roseburg, Oregon 97470

Date: August 17, 1981

At the $\frac{1}{4}$ corner common to section 34, T26S, R4W, W.M., and Section 3, T27S, R4W, W.M. I found a $2\frac{1}{2}$ " iron pipe with a 3" brass cap marked:



From which a:

1" iron axle is set alongside brass cap.

38" Oak original BT, with healed over face bears N10°E, 63.4 feet.

14" Walnut BT, with healed over face, bears S61°E, 238.6 feet.
(Record 239.6 feet).

B A Shaner