

**COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE**

INTERNATIONAL PAPER COMPANY

GARDINER OPERATION

Survey in the NW $\frac{1}{4}$ of Section 25, Township 23S, Range 8W, W. M.

Douglas County, Oregon
November 10, 1980

FILED *BS*
RECEIVED *2/8*

DEC 15 1980

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**

This survey was conducted by the International Paper Company survey crew to subdivide the NW $\frac{1}{4}$ of Section 25 in order to determine company ownership. Equipment used included a Jena 020 A Theodolite, Mac II H EDM and 200 foot chain.

A closed traverse, with a 1:5900 closure was run through the control corners. The CW 1/16 corner was set at the mid-point of the line between the W $\frac{1}{4}$ and C $\frac{1}{4}$ of the section. The NW 1/16 corner was set at the intersection of the center lines of the NW $\frac{1}{4}$ of the section as per paragraph 3-89, Bureau of Land Management Manual of Survey Instructions 1973.

The basis of bearing was a solar observation.

Corner Information

The following is a record of all corners found or set.

W $\frac{1}{4}$, Section 25, T23S, R8W

Found: 2 $\frac{1}{2}$ " iron pipe with Bureau of Land Management brass cap, dated 1964, from which:

- 16" cedar with healed face and Bureau of Land Management tag bears S33 $^{\circ}$ E, 47 links.
- 12" cedar with healed face and Bureau of Land Management tag bears S28 $^{\circ}$ W, 60 links.

N 1/16, Common to Sections 25 & 26, T23S, R8W

Found: 2 $\frac{1}{2}$ " iron pipe with Bureau of Land Management brass cap, dated 1964, from which:

- 16" cedar stump with visible scribing and Bureau of Land Management tag bears S37 $^{\circ}$ E, 34 $\frac{1}{2}$ links.
- 40" Douglas-fir stump with Bureau of Land Management tag bears N34 $^{\circ}$ W, 14.0 feet.

W 1/16, Common to Sections 24 and 25, T23S, R8W

Found: 2 $\frac{1}{2}$ " iron pipe with Bureau of Land Management brass cap, dated 1964, from which:

- 14" Douglas-fir with healed face and Bureau of Land Management tag bears S81 $^{\circ}$ W, 27 links.
- 14" hemlock with healed face and Bureau of Land Management tag bears N58 $^{\circ}$ W, 36 links.

**COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE**

CN 1/16, Section 25, T23S, R8W

Found: 5/8" iron rod, set by Forrest Hales in 1978, from which:
10" Douglas-fir with visible scribing and International Paper Company tag bears N66°E, 11.8 feet.
36" Douglas-fir with visible scribing and International Paper Company tag bears S84°W, 17.6 feet.

C¹/₄, Section 25, T23S, R8W

Found: 5/8" iron rod, set by Forrest Hales in 1978, from which:
8" Douglas-fir with scribing visible and International Paper Company tag bears S00¹/₂°E, 6.0 feet.
10" oak with scribing visible and International Paper Company tag bears N12¹/₂°W, 27.8 feet.

CW 1/16, Section 25, T23S, R8W

Found: Iron fence post set in unrecorded survey by Federal Highway Administration, 2/15/77, from which:
A reference tag on a 12" grand fir bears S35°W, 27.7 feet.

Set: 1/2" x 60" iron rod, from which:
16" grand fir with International Paper Company tag and scribed CW 1/16, S25, BT, bears S38¹/₂°W, 28.8 feet.
8" grand fir with International Paper Company tag and scribed CW 1/16, S25, BT, bears S65¹/₂°E, 25.7 feet.
Iron fence post described above, bears S56¹/₂°E, 1.2 feet.

NW 1/16, Section 25, T23S, R8W

Set: 1 1/2" x 36" galvanized iron pipe with brass cap, from which:
18" Douglas-fir with International Paper Company tag and scribed NW 1/16, S25, BT, bears N10°W, 18.2 feet.
36" Douglas-fir with International Paper Company tag and scribed NW 1/16, S25, BT, bears N49°E, 24.6 feet.

Respectfully submitted,

W. Carey Weatherly

W. C. WEATHERLY
P. O. Box 43
Gardiner, Oregon 97441



APPROVED:

John Marshall
JOHN MARSHALL

FILED
RECEIVED *VR*

DEC 15 1980

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.