

M 96-24

FILED
RECEIVED *BS*
MAR 28 1984

OREGON CORNER RESTORATION FORM


Section 21 Township 22S Range 9W

County Douglas Date 4-01-83

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

South $\frac{1}{4}$ Corner
Section 21



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Wofford, Rogers and Chatters
Cadastral Survey dated 1973-1979.


Monument(s) & Accessories Found: (Condition and Source)

Found 1975 B.L.M. Brass Cap set firmly in ground.

42" Fir, S25E, 20.2' (Scar Vis.), 1894 BT. Rec. S15E, 20.5'

58" Fir, N11E, 35.0' (Scar Vis.), 1894 BT. Rec. N22W, 36.3'

Monument Detail



Sketch

Monument Set (Procedures and Description)

New Accessories

None

Location & Comments

Corner lies on large
flat in heavy green
timber.

Compass Declination 20

Firm/Agency Roberts
Surveying Inc.

Address 29 West 29th St.
Eugene, Oregon 97405

Party Chief Les Roberts

Notes Ted Baker

Witness Stu Duce

Surveyor's Seal

Les Roberts