

M 96-41

FILED  
RECEIVED *JK*

APR 19 1984

OREGON CORNER RESTORATION FORM

Section 5 Township 20S Range 7W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County DOUGLAS/LANE Date 2/84

Corner Designation

NORTH 1/4 CORNER  
SECTION 5 ONLY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

1977 BLM SURVEY

Monument(s) & Accessories Found: (Condition and Source)

FOUND: 2 1/2" IRON PIPE WITH BRASS CAP "1977"



17" FIR S 55 E 23 1/2 (RECORDED: S 55 E, 361ks)

22" FIR S 72 W 20 3/8 (RECORDED: S 71 1/2 W, 321ks)

5 FOOT STEEL FENCE POST ALONGSIDE

Monument Detail

Sketch



REVISED 4/10/84

*Q & R.*

Monument Set (Procedures and Description)

---



---



---



---

New Accessories

---



---



---



---

Location & Comments

Surveyor's Seal

Compass Declination 20°

Firm/Agency PEEL BAKER

LAND SURVEYING, INC.

Address 1262 LAWRENCE ST

EUGENE OREGON 97401

Party Chief DAN BAKER

Notes

Witness DARYL STANLEY

