

M 97-51

FILED
RECEIVED *BF*

NOV 2 1984

OREGON CORNER RESTORATION FORM

Section 3 Township 215 Range 8W

County Douglas Date 10/12/84

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

$\frac{1}{4}$ $\frac{534}{53}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

1950 GLO DEPENDENT RESURVEY

Monument(s) & Accessories Found: (Condition and Source)


24" FIR STUMP, N17°E, 10.5 FT. (1950 BT)

28" FIR STUMP, S6½°W, 12.5 FT. (ORIGINAL)

(½" REBAR DRIVEN IN CENTER OF BT. STUMPS AND
4" X 4" POST FOUND EAST, 0.5 FT. FROM CORNER POINT)

Monument Detail

Sketch



Monument Set (Procedures and Description)

RESET 1" IRON PIPE WITH G.L.O. BRASS CAP "1950" AT
SLOPE DISTANCE FROM EXISTING BEARING TREES.

New Accessories

Location & Comments

Compass Declination 20°
 Firm/Agency PEEL BAKER
LAND SURVEYING, INC.
 Address 1262 LAWRENCE
EUGENE, OREGON
 Party Chief DAN BAKER
 Notes _____
 Witness DARYL STANLEY

Surveyor's Seal

Handwritten signature of Daniel W. Baker and a rectangular stamp.