

M 97-51

FILED
RECEIVED *BS*

NOV 2 1984

OREGON CORNER RESTORATION FORM

Section 10 Township 21S Range 8W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County DOUGLAS Date 10/12/84

Corner Designation

1/4 CORNER 59 | 510

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

1945 GLO DEPENDENT RESURVEY
1963 REMONUMENTATION

Monument(s) & Accessories Found: (Condition and Source)

2 1/2" IRON PIPE WITH BLM BRASS CAP "1963"

28" HEMLOCK, N 76 1/2° E, 80.1 FT. (1963 B.T.)

36" FIR, S 18° E, 38.7 FT. (1945 B.T.)

44" FIR, N 88° W, 44.4 FT. (1945 B.T.)

17" FIR SNAG, N 84° W, 31.2 FT. (ORIGINAL)

NORTHEAST ORIGINAL B.T. DOWN (SCRIBE VISIBLE)

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 20°
 Firm/Agency PEEL BAKER
LAND SURVEYING, INC.
 Address 1262 LAWRENCE
EUGENE, OREGON
 Party Chief DAN BAKER
 Notes _____
 Witness DARYL STANLEY

Surveyor's Seal

