

M 97-51

FILED
RECEIVED *ll*

NOV 2 1984

OREGON CORNER RESTORATION FORM

Section 10 Township 21S Range 8W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County DOUGLAS Date 10/12/84

Corner Designation

1/4 S10 | S11
CORNER

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.


1954 G.L.O. DEPENDENT RESURVEY

Monument(s) & Accessories Found: (Condition and Source)

- 1" IRON PIPE WITH G.L.O. BRASS CAP "1954"
- 36" CEDAR, S 53° E, 29.6 FT. (1954 B.T.)
- 58" FIR, S 58° W, 5.9 FT. TO FACE (ORIGINAL - NO MARKS)
- 38" CEDAR, N 76° W, 48.8 FT (1954 B.T.)

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 20°
 Firm/Agency PEEL BAKER
LAND SURVEYING, INC
 Address 1262 LAWRENCE
EUGENE, OREGON
 Party Chief DAN BAKER
 Notes _____
 Witness DARYL STANLEY

Professional
 LAND SURVEYOR
Daniel W. Baker
 DANIEL W. BAKER
 1976