


CERTIFIED RECORD OF LAND CORNER RECONSTITUTION

**History of original corner establishments:**

corner established in 1880 by Thiel.

Corner re-established with brass cap in 1918 by Collier on retracement.



**Description of corner evidence found:**

No monument found.

Found 14" maple brs. S25W 40.8 ft. - face grown over


24" cedar brs. N22W 22.4 ft. - face chopped out  
scribing visible

These BT's set in 1918

FILED  
RECEIVED  
MAR 9 1984  
COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE

**Description of monument and accessories established to perpetuate the original location of this corner**

Set 2"x30" iron pipe with brass cap mkd



Set 2 fence posts with signs + 5 ft. north facing west  
+ 5 ft. west facing north.

Office of ..... County of .....  
State of ..... I hereby certify that the within instrument was filed in this office  
for record on the ..... day of ..... 19..... at ..... o'clock ..... m. (signed)  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

REGISTERED  
OREGON  
LAND SURVEYOR

*Tom O. McCulloch*  
JULY 10, 1984  
TOM O. MCCULLOUGH  
650  
#110

Form R6-7100-57 (9/66)

#95

C.S. File No. 58/290-2

J-17.

C