

FILED
RECEIVED *fl*

APR 6 1984

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

OREGON CORNER RESTORATION FORM
Section 10 Township 30 S Range 7 W
County DOUGLAS Date JAN 13, 1984

Corner Designation
NE CORNER

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____


Monument(s) & Accessories Found: (Condition and Source)

FOUND BLM BRASS CAP FOR CORNER 4, 3, 10, 9
MARKED 1975
FOUND 11" FIR BEARS N 11° E 20⁶ FT. (REC. N. 3 1/2° E. 20.5')
SCIBING PARTIALLY GROWN OVER
 " 11" FIR BEARS N 79° W 43² FT " " " "
 " 7" FIR " S 60° E 30⁴ FT " " " "
 " 13" FIR " S 59° W 24⁸ FT " " " "

ALL BTS ARE IN GOOD CONDITION

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 20°
 Firm/Agency SUN STUDS
 Address P.O. BX 1127
ROSEBURG, OR
 Party Chief BW HOLT
 Notes _____
 Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Burton W. Holt

OREGON
OCTOBER 4, 1987
BURTON W. HOLT
418