

M 96-46

FILED
RECEIVED *BL*

OREGON CORNER RESTORATION FORM

APR 26 1984


Section 34 Township 19S Range 9W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 04-03-84

Corner Designation

East $\frac{1}{4}$ Corner
Section 34



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Tillman and Brooks Cadastral Survey dated 1957-1958.

Monument(s) & Accessories Found: (Condition and Source)


Found 1957 B.L.M. Brass Cap set firmly in ground.

16" Maple Snag, N45E, 16.1' (Scar Vis.), 1999 BT. Rec. N59E, 15.8'

40" Cedar Stump, N11W, 15.4' (No Marks), 1999 BT. Rec. N08W, 15.8'

15" Downed Cedar, N06E, 46.1' (Scar Vis.), 1957 BT. Rec. N63/4E, 44.2'

Monument Detail



Monument Set (Procedures and Description)

New Accessories

Set metal fence post beside brass cap. Wired survey attention sign to fence post.

Location & Comments

Corner lies on South slope about about 160' North of creek. Compass Declination 20 $\frac{1}{2}$

Firm/Agency Roberts

Surveying Inc.

Address 29 West 29th St.

Eugene, Oregon 97405

Party Chief Les Roberts

Notes Ted Baker

Witness Stu Duce.

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Les Roberts

OREGON
AUGUST 22, 1975
L. D. ROBERTS
1039

C.S. File No. 58/293-4A

OK Jim