

M 98-19

OREGON CORNER RESTORATION FORM

Section 30 Township 19S Range 8W

County Douglas Date 1-08-85

Corner Designation

S.W. Corner of Section 30.

(1)

30
31

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc. 1957 G.L.O. Survey by Tillman and Survey M87-78 by Roberts Surveying in 1981.

Monument(s) & Accessories Found: (Condition and Source)

Found 1957 G.L.O. Brass Cap set firmly in ground.

- 15" Downed Fir, N66E, 17.7' (Scar Vis.) , 1891 BT. Rec. N66½E, 17.2'
- 24" Fir , S38E, 16.1' (Scar Vis.) , 1891 BT. Rec. S40½E, 15.8'
- 18" Fir Stub , N4½E, 30.7' (Scribe Vis.), 1957 BT. Rec. N4 3/4E, 30.4'

Monument Detail



Monument Set (Procedures and Description)

New Accessories

None

Location & Comments

Corner lies on West slope in stand of heavy green timber.

Compass Declination 20½

Firm/Agency Roberts Surveying Inc.

Address 29 West 29th St.

Eugene, Oregon 97405

Party Chief Les Roberts

Notes _____

Witness _____

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Les Roberts

OREGON AUGUST 22, 1975 L. D. ROBERTS 1039