

N 93 - 11


OREGON CORNER RESTORATION FORM

Section 30 Township 19S Range 8W

County Douglas Date 1-16-85

Corner Designation

West 1/16 Corner  
South Line Sec. 30.



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. None

Monument(s) & Accessories Found: (Condition and Source)

---



---



---



---




---



---

Monument Detail

Sketch



10" FIR (SCRIBED)

N78°W 81.2'

SOUTH LINE SEC. 30

S40°W 31.4'

36" FIR STUMP (R.R. SPIKE)

BLAZED AND POSTED

SET ALUM PIPE & CAP

100'±

DRAW

Monument Set (Procedures and Description)

Set 2 1/2" x 30' Aluminum pipe and cap. Buried purple magnetic marker under aluminum pipe. See filed survey in Section 30.

New Accessories

10" Fir, N78W, 81.2' (Painted/Scrubed/Aluminum washer)

36" Fir Stump, S40W, 31.4' to R.R. Spike (Painted/ Alum. washer)

Set metal fence post beside aluminum pipe. Wired land survey monument sign to fence post.

Location & Comments

Corner lies on North slope about 100' West of small draw.

Compass Declination 20 1/2

Firm/Agency Roberts Surveying Inc.

Address 29 West 29th St. Eugene, Oregon 97405

Party Chief Ted Baker

Notes \_\_\_\_\_

Witness Stu Duce

Surveyor's Seal

