

M 96-61 A-B

FILED
RECEIVED *jt*

JUN 5 1984


OREGON CORNER RESTORATION FORM

Section 27 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-13-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____
Original GIO 1891, Thiel


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.



Monument Set (Procedures and Description)

Set by single proportion measure

New Accessories

38" D. Fir bears N 38° E, 60.2 ft., scribed 1/4 S27 BT
22" Maple bears N 69° W, 55.6 ft., scribed 1/4 S27 BT

Location & Comments

Surveyor's Seal

Set from survey for U.S. Forest Service Compass Declination 19°50'E
Firm/Agency Jackson & Prochnau, Inc.
Address P.O. Box 177
Albany, Ore. 97321
Party Chief K. Kendall
Notes _____
Witness Larry Griensewic

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

#181