

M 96-62

FILED
RECEIVED *el*

OREGON CORNER RESTORATION FORM


JUN 5 1984

Section 26 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-13-84

Corner Designation



- Condition Report Only
- Not Found
 - Renewed
 - Unrecorded
 - Surveyed In
 - Referenced Out

Previous Renewals/Surveys, etc. _____
Original GLO 1891, Thiel


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.



Monument Set (Procedures and Description)

Position determined from record (1891 GLO) latitude South from NE corner of Section 26 and record departure East from SW corner of Section 28 per recommendation from BLM.

New Accessories

16" D. Fir bears N 52° W 89.8 ft., scribed T21S R11W S26 BT
36" D. Fir bears N 59° E 27.5 ft., scribed T21S R11W S25 BT

Location & Comments

Surveyor's Seal

Set from survey for U.S. Forest Service Compass Declination 19°50'E
Firm/Agency Jackson & Prochnau, Inc.
Address P.O. Box 177
Albany, Ore. 97321
Party Chief K. Kendall
Notes
Witness Larry Griensewic

REGISTERED PROFESSIONAL LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

#174