

M 96-62

FILED
RECEIVED *BS*

OREGON CORNER RESTORATION FORM


JUN 5 1984

Section 26 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-10-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Set by original GLO survey 1891 (Thiel), 1960 BLM, 1974 Haines *M54-33*

Monument(s) & Accessories Found: (Condition and Source)

Fd. original BT : 62" D. Fir highstump bears N 29° E 31.02 ft., vis. scribe.

Monument Detail

Sketch

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.



Monument Set (Procedures and Description)

Corner set from original BT

New Accessories

10" Alder bears N 77° E, 42.8 ft., bark scribed X BT

5" Maple bears N 21° W, 49.3 ft., scribed X BT

Location & Comments

Set from survey for U. S. Forest Service Compass Declination 19° 50' E
 Firm/Agency Jackson & Prochnau, Inc.
 Address P.O. Box 177
Albany, Ore. 97321
 Party Chief K. Kendall
 Notes _____
 Witness Larry Griensewic

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305