

M 96-62

FILED
RECEIVED *BS*

OREGON CORNER RESTORATION FORM


JUN 5 1984

Section 35 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-10-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____
Set by original GIO 1891, Thiel _____


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 2" alum. cap on 24" x 1/2" iron rod in sandstone ridge, rockmound.



Monument Set (Procedures and Description)

Set by single proportion measure from S.E. corner of Section 26.

New Accessories

16" D. Fir bears S 3° E, 25.1 ft., scribed T21S R11W S36 CC BT
12" D. Fir bears S 59° W 23.5 ft., scribed T21S R11W S35 CC BT

Location & Comments

Surveyor's Seal

Compass Declination _____
Firm/Agency _____
Set from survey for _____ Jackson & Prochnau, Inc.
U.S. Forest Service Address P.O. Box 177
Albany, Ore. 97321
Party Chief K. Kendall
Notes _____
Witness Larry Griensewic _____

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W Prochnau
OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

#175
12 of 12