

M 96-62

FILED  
RECEIVED *BS*

JUN 5 1984


OREGON CORNER RESTORATION FORM

Section 26 Township 21S Range 11W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County Douglas Date 4-10-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.


Original GLO, 1891 Thiel

Monument(s) & Accessories Found: (Condition and Source)

Monument Detail

Sketch

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.



Monument Set (Procedures and Description)

Set by single proportion measure between the recovered witness point and the SW corner of Section 26.

New Accessories

23" D. Fir bears N 31° W 18.2 ft., scribed 1/4 S27 BT

26" D. Fir bears N 47° E, 16.2 ft., scribed 1/4 S26 BT

Location & Comments

Surveyor's Seal

Set from survey for U.S. Forest Service Compass Declination 19° 50' E

Firm/Agency

Jackson & Prochnau, Inc.

Address P.O. Box 177

Albany, Ore. 97321

Party Chief K. Kendall

Notes

Witness Larry Griensewic

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
SEPTEMBER 21, 1977  
JAMES W. PROCHNAU  
1305