

M 96-63 A&B

FILED
RECEIVED *BS*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 28 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-13-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc. NONE

Monument(s) & Accessories Found: (Condition and Source)
NONE

Monument Detail

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base. Rock mound.

Sketch



Monument Set (Procedures and Description)

Set by survey and subdivision of Section 28.

New Accessories

6" Alder bears S 34° E, 29.9 ft., bark scribed NW 1/16 S28 BT

Set R.M.= 3" alum. cap in 2 1/2" x 30" alum. pipe brs 53° 09' 45" W, 75.17 ft.

Location & Comments

Set from survey for U.S. Forest Service

Compass Declination 19° 50' E

Firm/Agency Jackson & Prochnau, Inc.

Address P.O. Box 177 Albany, Ore. 97321

Party Chief K. Kendall

Notes _____

Witness Larry Griensewic

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305