

M 96-64 AFB

FILED
RECEIVED *BS*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 33 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. NONE


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 2" alum. cap on $\frac{1}{2}$ " x 8" rebar in rock.



Monument Set (Procedures and Description)

Set by survey and subdivision of Section 33 on North bank of Umpqua River.

New Accessories

- 1 1/4" D. Fir bears N 71° E 48.1 ft., marked X BT
- 12" D. Fir bears S 63° W 19.8 ft., marked X BT

Location & Comments

Surveyor's Seal

Set from survey for U.S. Forest Service Compass Declination 19°50'E
Firm/Agency Jackson & Prochnau, Inc.
Address P.O. Box 177
Albany, Ore. 97321
Party Chief K. Kendall
Notes
Witness Larry Griensewic

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305