

M 96-64 A & B

FILED
RECEIVED *BL*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 33 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

NONE


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.



Monument Set (Procedures and Description)

Set from survey and subdivision of Section 34.

New Accessories

6" D. Fir bears N 86° E 21.0 ft., scribed 1/16 80 S34 BT

Set R.M.- 2" alum. cap on a 1/2" x 18" iron rod bears N84° 44' 41" W 58.0 ft.

Location & Comments

Surveyor's Seal

Set from survey for
U.S. Forest Service

Compass Declination 19° 50' E

Firm/Agency

Jackson & Prochnau, Inc.

Address P.O. Box 177

Albany, Ore. 97321

Party Chief K. Kendall

Notes

Witness Larry Griensewic

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau
OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305