

M 96-64 A&B

FILED
RECEIVED *RS*

JUN 6 1984


OREGON CORNER RESTORATION FORM

Section 33 Township 21S Range 11W

County Douglas Date 4-16-84

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Jackson & Prochnau, Inc., 1978 CS 58/186

Monument(s) & Accessories Found: (Condition and Source)

Fd. Jackson & Prochnau BT's:

28" Maple bears S 46° E 23.0 ft., (Rec. S43°E, 24.1 ft.) vis. scribe


31" Fir bears N 33° E 28.2 ft., (rec. N38° E 26.0 ft.,) healed face.

Fd. 1/2" iron rod set by Jackson & Prochnau, LS 1305 in 1978.

Monument Detail

Sketch

Replaced iron rod with 3" alum. cap in 2 1/2" x 30' alum.
pipe with flared base, rockmound.



Monument Set (Procedures and Description)

New Accessories

NONE

Location & Comments

Surveyor's Seal

Set from survey for Compass Declination 19°50' E
U. S. Forest Service Firm/Agency
Jackson & Prochnau, Inc.
Address
P.O. Box 177, Albany, Ore. 97321
Party Chief K. Kendall
Notes
Witness Larry Griensewic

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305