

M 96-65 A & B

FILED
RECEIVED *BS*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 34 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Original GIO 1878 Byars, 1959 Hootman M 15-23, 1964 OSBF M 27-28,
1978 Jackson & Prochnau CS# 58/186

Monument(s) & Accessories Found: (Condition and Source)


- Fd. 1 1/2" iron pipe (no record) with screw on cap.
- Fd. Hootman BT: 26" Forked Spruce bears N 70° E 16.3 ft. (rec. N 70° W 14.5 ft.)
healed face.
- Fd. orig. BT: 62" Spruce bears S 30° E 50.1 ft. (rec S 31 1/2° E 47.5 ft.) healed face

Monument Detail

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.

Replaced iron pipe with monuments

Sketch



Monument Set (Procedures and Description)

New Accessories

NONE

Location & Comments

Set from survey for
U.S. Forest Service

Compass Declination 19°50'E

Firm/Agency _____

Jackson & Prochnau

Address P.O. Box 177

Albany, Ore. 97321

Party Chief K. Kendall

Notes _____

Witness Larry Griensewic

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

195 T21-11