

M 96-65 A & B

FILED
RECEIVED *B*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 34 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Original GLO 1878 Byars, 1891 GLO Thiel, Lewis PE 722, 1939.


Monument(s) & Accessories Found: (Condition and Source)

Fd. Lewis', PE 722, 1939 BT's: 47" forked Spruce bears S 10° E 5.0 ft., healed face
43" Spruce bears S 75° W 24.0 ft., healed face.

Monument Detail

Set W.C. 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, bears N 4° 03' 44" W 30.00 Ft. from true corner.

Sketch



Monument Set (Procedures and Description)

Set from Lewis' BT's.

New Accessories

6" Alder bears S 56° E 10.6 ft., bark scribed X BT

Set R.M. - 3" alum. cap in 2 1/2" x 30" alum. pipe bears N 71° 30' 24" W
50.82 ft. from W.C.

Location & Comments

Set from survey for
U.S. Forest Service

Compass Declination 19° 50' E

Firm/Agency _____

Jackson & Prochnau, Inc.

Address P.O. Box 177

Albany, Ore. 97321

Party Chief K. Kendall

Notes _____

Witness Larry Griensewic

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau
OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

#193