

M 96-65 A&B

FILED
RECEIVED *ES*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 34 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
 - Renewed
 - Unrecorded
 - Surveyed In
 - Referenced Out

Previous Renewals/Surveys, etc. _____

Orig. GLO 1891 Thiel; 1959 Hootman M 15-23

Monument(s) & Accessories Found: (Condition and Source)

Fd. 1" iron pipe set by Hootman, IS 399, loose and leaning East, bears S 3°05'28" E 18.82 ft. from true position.


Fd. Hootman BT's from his monument: 36" D. Fir snag bears S 39° E 58.0 ft., healed 24" D. Fir bears S 65° W 26.0 ft., healed face.

12" D. Fir bears N 19° E 41.0 ft.

Monument Detail

Set 3" alum. cap in 2½"x 30" alum. pipe with flared base, rockmound.

Sketch



Monument Set (Procedures and Description)

Set by single proportion measure

New Accessories

24" D. Fir bears S 38° W 37.5 ft., scribed T21S R11W CC S33 BT

34" D. Fir bears S 58° E 65.0 ft., scribed T21S R11W CC S34 BT

Location & Comments

Set from survey for Compass Declination 19°50'E
U.S. Forest Service Firm/Agency
Jackson & Prochnau, Inc.
Address P.O. Box 177
Albany, Ore. 97321
Party Chief K. Kendall
Notes
Witness Larry Griensewic

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau
OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

#185