

M 96-65 A & B

FILED  
RECEIVED BS

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 34 Township 21S Range 11W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. NONE


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 2" alum. cap on a 1/2" x 5' rebar.



Monument Set (Procedures and Description)

Set by survey and subdivision of Section 34. Corner set on property line, as determined from a mean course between the S 1/2 of the East line of Section 34, and the North-South center line of section 34.

New Accessories

42" Spruce bears N 15° W 75.5 ft., scribed X BT  
36" Spruce bears N 17 1/2° E 74.3 ft., scribed X BT

Location & Comments

Surveyor's Seal

Set from survey for U.S. Forest Service Compass Declination 19°50'E  
Firm/Agency Jackson & Prochnau, Inc.  
Address P.O. Box 177  
Albany, Ore. 97321  
Party Chief K. Kendall  
Notes \_\_\_\_\_  
Witness Larry Griensewic

