

M 96-65 A 1/2 B

FILED  
RECEIVED BS

JUN 6 1984


OREGON CORNER RESTORATION FORM

Section 34 Township 21S Range 11W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County Douglas Date 4-10-84

Corner Designation



- Condition Report Only
- Not Found
  - Renewed
  - Unrecorded
  - Surveyed In
  - Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Original 1891 GLO, Thiel


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.



Monument Set (Procedures and Description)

Set by single proportion measure from SW corner of Section 26.

New Accessories

3 1/4" D. Fir bears S 13° W, 40.3 ft., scribed T21S R11W CC S34 BT

32" D. Fir bears S 40° E, 35.5 ft., scribed T21S R11W CC S35 BT

Location & Comments

Surveyor's Seal

Set from survey for U. S. Forest Service Compass Declination 19°50' E  
Firm/Agency \_\_\_\_\_

Jackson & Prochnau, Inc.

Address P.O. Box 177

Albany, Ore. 97321

Party Chief K. Kendall

Notes \_\_\_\_\_

Witness Larry Griensewic

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*James W. Prochnau*

OREGON  
SEPTEMBER 21, 1977  
JAMES W. PROCHNAU  
1305