

M 96-65 A & B

FILED
RECEIVED *BJ*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 34 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.
NONE


Monument(s) & Accessories found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.



Monument Set (Procedures and Description)

Set from survey and subdivision of Section 34 on North bank Umpqua River.

New Accessories

- 18" D. Fir bears S 76° W 20.0 ft., scribed X BT
- 15" D. Fir bears N 69° W 15.9 ft., (18.5 at 31°) scribed X BT

Location & Comments

Surveyor's Seal

Set from survey for Compass Declination 19°50'E
U.S. Forest Service Firm/Agency _____
 _____ Jackson & Prochnau, Inc.
 _____ Address P.O. Box 177
 _____ Albany, Ore. 97321
 _____ Party Chief K. Kendall
 _____ Notes _____
 _____ Witness Larry Griensewic

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305