

FILED *J*  
RECEIVED *JR*

FEB 11 1985

OREGON CORNER RESTORATION FORM

Section 34/35 Township 31S Range 7W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County Douglas Date 2/5/85

Corner Designation

1/4 COR 34/35

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_


1964 Cadastral resurvey

Monument(s) & Accessories Found: (Condition and Source)

<u>Cadastral Brass Cap</u>	<u>1964 Cad. Survey</u>	<u>ok</u>
<u>16 D.Fir 514 E 58<sup>L</sup></u>	<u>" " "</u>	<u>ok</u>

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

3 1/2" D. fir 541W 13<sup>B</sup> scribed "1/4 S 34 BT"

Location & Comments

Cor is on East slope  
partly buried, on the  
lower side of a dirt  
fill from a cat fire  
trail road.  
Set steel fence post  
along side Brass Cap.

Compass Declination 21°  
 Firm/Agency \_\_\_\_\_  
Roseburg Lbr. Co.  
 Address P.O. Box 1083  
Roseburg, OR 97470  
 Party Chief HW Johnstone  
 Notes \_\_\_\_\_  
 Witness \_\_\_\_\_

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Howard W. Johnstone*

OREGON  
MAY 13, 1960  
HOWARD W. JOHNSTONE  
498

#123<sup>X</sup>

C.S. File No. 58/296<sup>C</sup>