

2-18-76

22/23  
27/26

T 30S 28W

(SEE DEN. #17)

FD: 1" I. PIPE EXTENDING 12" ABOVE GROUND, FIRMLY

SET, WITH BRASS CAP ATTACHED MARKED:

COUNTY SURVEYOR'S OFFICE

S 22 | S 23

S 27 | S 26

T 30S 28W

1958

FROM WHICH WE FIND REMAINS OF THREE ORIGINAL

BEARING TREES AS FOLLOWS:

THE NE AND NW ORIGINAL BT'S HAVE

BOTH BLOWN DOWN, HOWEVER THEY APPEAR

TO HAVE STOOD IN THEIR PROPER LOCATIONS.

AN ORIG. 15" FIR, NOW AN 18" SNAG BEARS

S 57° E 13<sup>9</sup> FT., WITH SCRIBING "8W S 26"

VISIBLE ON PREVIOUSLY OPENED BLAZE.

C

#118 ✓

C. S. File No. 59/8-2

PAGE 2

DIETZGEN NO. 385-5

NEW SW BT 25" D. Ac

S 34½° W

T30S R8W S27CS BT

69<sup>6</sup> @ 10° .9848 68<sup>5</sup>

7" G. Ac

N 42° W

"T30S R8W S22CS BT"

86° LVL

1" I. PIPE EXTENDING 12" ABOVE GROUND

COUNTY S O

526/500

521/500

T30S R8W

1958

WE FIND NO TRACE OF THE ORIGINAL SW  
BEARING TREE.

WE FIND THE COUNTY SURVEYOR'S 1958 BT'S  
(SEE REN. #17) AS FOLLOWS:

A 20" NOW 22" D. FIR, ALIVE AND WELL-  
HEALED, BEARS  $S 32^{\circ} E 40^{\circ}$  FT.

AND AN 18" D. FIR, NOW A SNAG, WITH SCRIBING

"T30S R8W S27 CS BT" VISIBLE ON A

DOUBLE BLAZE BEARS  $S 57^{\circ} W 31^{\circ}$  FT.

WE MARK TWO ADDITIONAL BT'S AS

FOLLOWS:

A 25" D. FIR BEARS  $S 34\frac{1}{2}^{\circ} W 68^{\frac{5}{8}}$  FT.,

SCRIBED "T30S R8W S27 CS BT"

ON A DOUBLE BLAZE.

AND A 7" GRAND FIR BEARS  $N 42^{\circ} W$

$86^{\circ}$  FT, SCRIBED -

"T303 RBW 522 CS BT" ON A  
DOUBLE BLAZE.

NOTE THE AREA NW OF THIS CORNER HAS BEEN  
CLEARCUT. THIS CORNER IS LOCATED  
APPROX. 100 FT. EAST OF ROAD 30-8-25  
LEADING TO LIVE OAK MTN.

COMPASS DECLINATION SETTING: 20° EAST

2-18-76

Gary L. Anglet

M. LENORA LADIG

A. VIC CANGIE

OK *[Signature]*