

8124176

T 305

R
E
G
E
S

1/4 S 25

R
S
WSEE REN. # 195 T30-6
242 T30-5

①

FOUND:

A BRASS CAP IN GOOD CONDITION SET BY JOHN M. POWELL & CREW IN 1969. A STEEL FENCE POST WAS SET BY CORNER.

A 12" OAK BEARS S 26° W; 127.4'. TREE IS ALIVE AND SHOWS HEALED BLAZE.

A 10" W. OAK BEARS S 82° W; 262.6'. TREE IS ALIVE AND SHOWS HEALED BLAZE.

AT THE REQUEST OF LANDOWNER WE REMOVE FENCE POST AND LOWER BRASS CAP FLUSH WITH GROUND SO AS NOT TO INJURE OR CAUSE INJURY TO HIS LIVESTOCK.

#219 T30-6 ✓
#268 T30-5 ✓

C.S. File No. 59/18-22

C

812A176

T3DS

SEE REV. # 195

R 6 W	1/4 S 25	R 5 W
-------------	----------------	-------------

(2)

WE STAMP "RESET 1976" ON
DCSO 1969 BRASS CAP.

DIETZEN NO. 385-B

COMPASS DEC. 20th 1976

A. Dietzen

JIM COOK

OK
[Signature]

G. S. File No. 59/18-22