

11 | 22 | 76

T 22 S

1/4

S 4 | S 3

R 5 W

SEE REN. 11, S 4-A

(1)

FOUND:

HAINES "T" IRON AND WASHER AT CORNER
POINT. ^{REN # S 4 A " 11 "} FROM WHICH:

A 12" NOW 18" B. OAK BEARS S 57° E; 87'.
TREE IS ALIVE BUT IN POOR CONDITION.
SHOWS HEALED BLAZE.

A 16" NOW 29" FIR BEARS N 30 1/2° W
(REG. N 39° 13' W); 40.4'. HEALTHY
AND SHOWS HEALED BLAZE.

SET:

A 1" X 30" I.P. WITH BRASS CAP
STAMPED: DOUGLAS CO. SURVEYOR

T 22 S

1/4

S 4 | S 3

R 5 W

1976

#156 ✓

U.S. File No. 59/26-17

DIETZEN 110. 3885 0

11/22/76

T22S

1/4

S4 | S3

RSW

SEE REN. # 11,51-A

(2)

WE REPLACE FOUND "T" IRON ON
NORTH SIDE OF BRASS CAP.

NEW TREE :

A 16" R. CEDAR BEARS N 3° E; 27.5'
MARKED "1/4 S 3 CS BT"

NOTE: CORNER LIES APPROX. 50' SOUTH
OF A SW₁ DRAW IN AN OLD EAST-
WEST FENCE.

COMPASS DEC. 20° E.

A. Victor Campie

MIKE TOMPKINS

OK *[Signature]*

C.S. File No. 59/26

DIETZEN NO. 385-S