

RENEWAL

1-3-77

T 31 S

R 1/4 R

T 525/530⁶
W W

SEE RENEWALS # 18 (R W) & # 51 (R W)

FOUND.

1. 3/4 INCH BY 24 INCH ~~IRON PIPE~~
IRON PIPE AT 1/4 CORNER FIRMLY
SET.

ALSO FOUND 3' X 3" SQUARED
WOODEN POST.

2. ORIGINAL IS NOW 24 INCH DIAM.
FIR BEARS N 48° E, 4° FEET
(REC. N 47° E). TREE HAS BEEN
~~REMOVED~~ BARK SCRIBING " 1/4
S B T ".

3. A CEDAR 30 NOW 32 INCH DIAM.
BEARS S 47° W, 15 1/2 FEET (REC.
S 42° W). TREE HAS PARTIALLY
OPENED BLAZE, SCRIBING VISIBLE
" 1/4 ".

98 T 31-7 ✓
136 T 31-6 ✓

C. S. File No. 59/29-2 C

RENEWAL

SET 1" X 30" IRON PIPE WITH BRASS
CAP ATTACHED AT 1/4 CORNER,
CAP IS STAMPED;

" DOUGLAS COUNTY SURVEYOR "

	T 31 S	
R	1/4	R
7	S 25 / 330	6
W		W

1977

WE PLACE IRON PIPE AND WOODEN
POST BESIDE BRASS CAP. CAP
IS SET IN MOUND OF STONE.

NO NEW B.T.'S NECESSARY

MAGNETIC DECLINATION 20°E

OK
[Signature]

1-3-77

[Signature]
LARRY E. MONREAN

K. CHENEY

P. L. EARLE

C.S. File No. 59/29-2

DIETZEN NO 385-B