

1-10-77

T. 29S R7W

20 | 21

1/4

(SEE 1966 BLM DEPENDENT RESURVEY)

Fp:

2 1/2" IRON PIPE SET FLUSH IN THE GROUND
NEAR THE BOTTOM OF THE CUTBANK, APPROX.
10 FT. WEST OF THE WEST EDGE OF THE AC
OF OLALLA ROAD, WITH BRASS CAP MARKED:

U.S. DEPT. OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

T 29S R7W

1/4

S20 | S21

1966

(NOTE: THIS CAP IS ORIENTED FACING SOUTH.)
WITH STEEL FENCE POST ALONGSIDE,

FROM WHICH:

A 13" NOW 14" D. FIR, ALIVE AND WELL-
HEALED, BEARS S 65° E 96 ± FT.

#218 ✓

C. S. File No. 59/29-5 PAGE 1 ✓

ILLINOIS 385-S
NO. 2

AND A 13" NOW 13" D. FIR SNAG, BURNED AND
WELL-HEALED, BEARS N 76° W 28⁴ FT.

WE MARK A NEW BT AS FOLLOWS:

A 13" D. FIR BEARS N 50¹/₂° E 192³/₄ FT.,
SCRIBED "1/4 S ZICS BT" ON A DOUBLE
BLAZE.

COMPASS DECLINATION SETTING: 20° EAST

1-10-77

Gary L. Langitz

A. VICTOR CANOIE

MIKE TOMPINS

OK
[Signature]