

14089

U S GENERAL LAND OFFICE SURVEY

1/4 53

1937

DATE: 2-24-77

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) BASS CAP STAMPED
AS SHOWN ABOVE, BENT OVER 90°
By LOGGING ACTIVITIES, REMOVED &
STRAIGHTENED PIPE. RE-SET BRASS
CAP & IRON PIPE MONUMENTS USING
ACCESSORIES. (TOWNSHIP & RANGE
NOT MARKED ON B.C.) T30S, R1E

Accessories Found: (Condition and Source) _____

^{LIVE}
A 27" DOUGLAS FIR BEARS S35°W, 75.9'
HAS HEALED SCAR, PLACED ^{COUNTY} B.T. SIGN,
A 41" DOUGLAS FIR STUMP BEARS S50°E,
63.36' HAS A HEALED SCAR. PLACED A
COUNTY B.T. SIGN ON STUMP,

#138 - T29-1E ✓
 #34 T30-1E ✓

RENEWAL

Monument Set: (Procedure and Description) _____

~~NOTE~~

REPLACED ORIGINAL P. MONUMENT,
FROM ACCESSORIES.

New Accessories: (Description) _____

~~NOTE~~

A 32" DOUGLAS FIR BEARS S 73° E,
54.9' ^{DOUBLE} BLAZED & SCRIBED "1/4 53 CS BT"
PLACE COUNTY B.T. SIGN ON IT.

Location and Comments:

CORNER IS 850'
EAST OF F.S.
ROAD # 2930A

18° 30' E
U.S.F.S.
DENNIS GAYLORD
" " "
WALT BARTON

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
