

DATE: 3-17-77

J. S. GENERAL LAND OFFICE SURVEY  
S 22 | S 23  
1/4

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 1923 \_\_\_\_\_

Monument(s) Found: (Condition and Source) <sup>2 1/2"</sup> FOUND BRASS CAP  
STAMPED AS SHOWN. BRASS CAP 24" ABOVE  
GROUND & LEANING TOWARD CENTER OF  
DECOMPOSED STUMP, ALL THAT REMAINS  
OF THE ORIGINAL CORNER TREE.

TOWNSHIP & RANGE NOT STAMPED  
ON BRASS CAP. (T 30S, R 1W)

Accessories Found: (Condition and Source) \_\_\_\_\_

A FIR TREE BEARS S 82° E, 57.42' &  
IS BLOWN DOWN - HAS HEALED BLAZE.

A FIR BEARS S 35° W, 20.46' &  
IS BLOWN DOWN - HAS HEALED BLAZE

#153 ✓

RENEWAL

Monument Set: (Procedure and Description) I REMOVE  
BRASS CAP & IRON PIPE (WHICH IS LOOSE)  
AND PLACE IN EXACT CENTER OF  
THE DECOMPOSED ~~CENTER~~ REMAINS OF  
THE ORIGINAL CORNER TREE. TOP OF  
BRASS CAP IS SET FLUSH WITH GROUND.

New Accessories: (Description) \_\_\_\_\_

A 6" WHITE FIR BEARS N59°30'E  
27.3' ~~BEARS~~ SCRIBED "1/4 S 23 CS BT"  
ON A DOUBLE BLAZE.

A 6" WHITE FIR BEARS S34°30'W, 16.6'  
SCRIBED "1/4 S 22 CS BT" ON A DOUBLE BLAZE.

Location and Comments:

CORNER LIES ON A  
NORTH SLOPE, SOUTH  
OF JACKSON CRK.

IN A RECENTLY LOGGED  
AREA.

20° E  
U.S. F.S.  
DENNIS GAYLORD  
" "

WALTER BARTON

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

*OK [Signature]*