

DATE: 4-12-77

T 235

R6W		R5W
51		56
512		57

1943

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s SEE 1943 RESURVEY

Monument(s) Found: (Condition and Source) FOUND U.S. GENERAL

LAND OFFICE SURVEY BRASS CAP ON 2" PIPE (O.D.)

" T 235 "

7" ABOVE GROUND MARKED R6W R5W

51 | 56

512 | 57

1943

Accessories Found: (Condition and Source) A FIR STUMP, 24" DIA.,

BEARS S55°E (REC. S10°E) 21¹/₂ FT. DIST., BLAZED AND MARKED

"R5W T235 57."

A FIR STUMP, 16" DIA., BEARS S45°W 42¹/₂ FT. DIST.

(REC. 44°), BLAZED AND MARKED "T235 512 BT."

REMAINS OF FIR STUMP, CENTER OF ROOT HOLE BEARS

N5°W, 14¹/₂ FT. DIST.

#103 T23-5 ✓

#69 T23-6 ✓

Page 1 of 1
C. S. File No. 5931-24 C

A DOUGLAS FIR WINDFALL, 41" DIA., BEARS N49°E
APPROX. 32³/₄ FT DIST. TO CENTER OF ROOT HOLE, SINGLE
BLAZE AND MARKED "T235 R5W S6 BT".

A DOUGLAS FIR, 36" DIA. BEARS S21°E, 31¹/₂ FT DIST.
WITH WELL HEALED BLAZE.

RENEWAL

~~Monument Set: (Procedure and Description)~~

A CEDAR, 28" DIA., BEARS N53¹/₂°W (REG. N55°W), 47⁵/₈
FT. DIST., WITH WELL HEALED BLAZE FACING N70°E.

New Accessories: (Description) A MADRONE, 11" DIA., BEARS
S68°W, 19¹/₄ FT. DIST., DOUBLE BLAZED AND MARKED
"T235 R6W S12 CS BT".

A DOUGLAS FIR, 11" DIA., BEARS N56°E, 51⁰/₂ FT DIST,
DOUBLE BLAZED AND MARKED "T235 R5W S6 CS BT".

Location and Comments:

20°E
DCSO
LARRY E. MONREAN
Robert B. Kimberling

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK 