

COUNTY SURVEYOR'S  
T 26 S R 14 E OFFICE  
S 33 } S 34

DATE: 5-19-77

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 1977

Monument(s) Found: (Condition and Source) NONE -

ORIGINAL G.L.O. BRASS CAP APPARENTLY  
DESTROYED IN LOGGING OPERATIONS.

Accessories Found: (Condition and Source) \_\_\_\_\_

40" DOUGLAS FIR STUMP, PARTLY DECOMPOSED  
OPEN & FIND SCRIBING & REVERSE "S 34 BT"  
BEARS S 36° E, 17.16'

B.T. TO THE NW HAS BEEN DESTROYED  
WHEN FISH CRK CANAL WAS BUILT. IT  
LIES IN BORROW AREA.

#2 ✓

RENEWAL

Monument Set: (Procedure and Description)

SET 2 1/2" BRASSCAP ON A 1" G.I. PIPE,

STAMPED AS SHOWN ON REVERSE,

FROM FOUND B.T. STUMP. BRASS CAP

IS 8' EAST OF TOP OF BORROW AREA CUT,  
AND 200' ± EAST OF FISH CRK. CANAL.

New Accessories: (Description) A 58" DOUGLAS FIR

BEARS N 81° E, 36.4' SCRIBED "1/4 S 34 CS BT"

ON A SINGLE BLAZE.

A 11" DOUGLAS FIR BEARS N 74 1/2° W, 298.3'

SCRIBED "1/4 S 33 CS BT" ON A DOUBLE BLAZE

THIS B.T. IS APPROX 25' WEST OF CANAL.

Location and Comments:

DECLINATION DETERM-  
INED AT COR <sup>28/27</sup> 33/34,

A LINE SOUTH TO THIS  
CORNER FALLS 30° E,  
OF THE CORNER.

18° E

U.S.F.S.

DENNIS GAYLORD

" "

WALTER BARTON

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK *[Signature]*