

* 7235 RIW

~~7245 RIW~~

DATE: 8-25-77

31
6

Per
Research
6-10-97
DCSO X

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) NONE - WEYERHAEUSER SURVEYOR, FRANK WILLIAMS, FOUND SCRIBED BT APPARENTLY BURIED IN NEW LOGGING ROAD FILL.



RENEWAL

Monument Set: (Procedure and Description) NONE

ew Accessories: (Description) NONE

Location and Comments:

DCSO
R B KIMBERLING
R.B. Kimberling
M.W. CLINE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP 24S

RANGE 1W

SECTION 6

CORNER N $\frac{1}{4}$

COUNTY Douglas

OREGON

GLO Survey Record 1894

Present condition 8/16/1975:

Basalt stone 24"x20"x12" marked 1/4
on north face.

Original stone not identified;
several large stones have slid
down steep hillside to creek
bottom, many are fractured.

6" Fir N62W 7 lks. 4.6'

Not found.

4" Fir S35W 8 lks. 5.3'

8"x8" Hemlock snag (not Fir) down
with curved portion of root still
in its original position. Overgrowth
was chopped away to expose scribed
"1/4S" on upperface and "BT" on
lower face.

Drove 3" x 5' Cedar post N35E 5.3' from center of roothole of down scribed
BT. This corner will soon be further monumented by a current Triangle
Engineering Company subdivision of Sec. 6.

Present: N. Juliano

D. Peel

G. McChesney

August 16, 1975

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Frank D. Williams

OREGON
1975

C. S. E. No. 59/38-20