

T295 R6W

518 | 517

519 | 520

DATE: 10-3-77

Condition Report Only

Not Found

X Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s 1958 RESURVEY

Monument(s) Found: (Condition and Source) A 2" X 30" IRON PIPE
(LOOSELY) WITH BRASS CAP SET 20" ABOVE GROUND, CAP BROKEN
AND TORN PARTLY OFF, MARKED "U.S. CADASTRAL SURVEY"

T295 R6W

518 | 517

519 | 520

1958

Accessories Found: (Condition and Source) A FIR, 18" NOW 20" DIA.,
BEARS N8°E 29⁷ FT. WITH SINGLE WELL HEALED BLAZE.
A MADRONE SNAG, 4" NOW 8" DIA., 2⁰ FT. HIGH AND PARTLY
PUSHED OVER, BEARS S63°E 11⁷ FT. (REG. 12⁵ FT.). A FIR,
25" NOW 28" DIA., BEARS N37°W 23⁸ FT. WITH TWO
WELL HEALED BLAZES (ONE FACES EAST).

#235 ✓

C

RENEWAL

Monument Set: (Procedure and Description) A 1" X 36" IRON PIPE
WITH BRASS CAP SET 4" ABOVE GROUND AND
MARKED "DOUGLAS COUNTY SURVEYOR"
T295 R6W
S18 | S17
S19 | S20
1977

New Accessories: (Description) A 8" DIA. MADRONE BEARS
S 85 1/2° W 27° FT., DOUBLE BLAZED AND MARKED
"T295 R6W S19 CS BT". A 6" DIA. W. DAK BEARS
S 32° E 24° FT., DOUBLE BLAZED AND MARKED
"T295 R6W S20 CS BT".

Location and Comments:
CORNER IS IN
NORTH - SOUTH CAT
TRAIL

20° E
DCSO
R. B. KIMBERLING
R. B. Kimberling
M. W. CLINE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]