

T295 R7W

DATE: 10-12-77

19 | 20
N 1/6

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) NONE

#247 ✓

C

RENEWAL

Monument Set: (Procedure and Description) CORNER LOCATION DETERMINED

BY SURVEY. AT THE CORNER POINT, WE SET A 1" X 30" I. PIPE, 20" IN THE
TO BEDROCK
GROUND, WITH BRASS CAP ATTACHED, MARKED: DOUGLAS COUNTY SURVEYOR

T29S R7W
N 1/4
S19 | S20

1977

New Accessories: (Description)

AN 1/8" P. PINE, SCRIBED "N 1/4 S19 CS BT" ON A DOUBLE BLAZE,
BEARS N 51° W 31 1/4 FT.

AND A 1/2" I. CEDAR, SCRIBED "N 1/4 S20 CS BT" ON A DOUBLE BLAZE,
BEARS N 18° E 20° FT.

Location and Comments:

CORNER LOCATED ALONG
OLD N-S CUTTING LINE.

20° EAST
DOUGLAS CO. SURVEYORS OFF.
GARY L. LANGLITZ
Gary L. Langlitz
LARRY E. MONREAN
PETER L. EARLE
STEPHEN J. FLAUSE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]

~~287~~