

T255
RBW | RTW
1/4 512 | 57

DATE: Nov 14, 1977

Condition Report Only
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewal #'s ^{T25-7} #64, #71 #14 T25-8

Monument(s) Found: (Condition and Source) A 1" x 36" IRON PIPE LAYING
IN CROTCH OF TREE, BENT, WITH BRASS CAP MARKED
"COUNTY SURVEYORS OFFICE"
T255

RBW | RTW
1/4 512 | 57
BLM 1964
1961

A 3/4" x 30" IRON PIPE, BENT AND MANGLED

(OBVIOUSLY DISLOCATED) BEARS N72°W 7 1/2 FT. FROM CORNER
RESET FROM BEARING TREES (REC. SET BY KERR 1954, A 1/2"
IRON PIPE BEARS S79 1/2°W 7 1/2 FT. ACCORDING TO BLM 1964,
S80°W 7 1/2 FT. ACCORDING TO REN #64).

Accessories Found: (Condition and Source) A WHITE OAK, 24" NOW 37"
DIA., BEARS N7°W (REC. N6 1/2°W) 534 1/2 FT. WITH VISABLE SCRIBING
"S12 BT" IN PARTLY HEALED UPPER BLAZE AND "BT" IN CHOPPED
OPEN LOWER BLAZE. A 9" HIGH "K" IS CARVED IN SOUTH SIDE
OF TREE (O.B.T.), A WHITE OAK, 20" NOW 24" DIA., BEARS
N87°E 255 1/2 FT., WITH A WELL HEALED BLAZE

#103 T25-8 X

#117 T25-7 X

Page 1 of 1

C. S. File No. 59/42-12

C

RENEWAL

Monument Set: (Procedure and Description) I STRAIGHTEN AND
RESET BRASS CAP, 0⁴ FT. ABOVE GROUND, WITH DISTANCES
CONTROLLING PLACEMENT USING HEWLIT PACKARD ELECTRONIC
MEASUREMENT TO O.B.T. AND TRANSIT / STEEL TAPE MEASUREMENTS
ON ALL OTHER DISTANCES. I STAMP "RESET 1977" ABOVE "BLM 1964".

New Accessories: (Description) A 12" DIA. WALNUT TREE
BEARS 533°W 5⁶ FT, BUT I DO NOT MARK TREE.

Location and Comments:	<u>20°E</u>	Compass Declination
<u>SET A STEEL FENCE</u>	<u>DCSO</u>	Agency
<u>POST 12 FT. SOUTH OF</u>	<u>R. B. KIMBERLING</u>	Party Chief
<u>B.C. WITH SURVEY</u>	<u>R. B. Kimberling</u>	Notekeeper
<u>MARKER SIGN ATTACHED.</u>	<u>P. L. EARLE</u>	Witnesses
<u>CORNER IS APPROX. 80 FT</u>		
<u>SOUTH OF COUNTY ROAD</u>		
<u>IN OLD WALNUT ORCHARD</u>		

ok [signature]