

DATE: 11-21-77

T295 R7W

E 1/2
C — C
S18

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) NONE

#253 ✓

RENEWAL

Monument Set: (Procedure and Description) AT THE CORNER POINT AS

DETERMINED BY SINGLE PROPORTIONATE MEASUREMENT, WE SET A

1" x 30" I. PIPE 26" IN THE GROUND, WITH BRASS CAP ATTACHED, MARKED:

DOUGLAS COUNTY SURVEYOR

T29S R7W

E 1/4

C ——— C

S 18

New Accessories: (Description) _____

1977

A 16" W. OAK BEARS S 10° E 140 2/3 FT., SCRIBED "CE 1/4 S 18 CS BT"

ON A DOUBLE BLAZE.

AND A 10" D. FIR BEARS S 89° E 79 1/4 FT., SCRIBED "CE 1/4 S 18 CS BT"

ON A DOUBLE BLAZE.

Location and Comments: _____

20° EAST

Compass Declination

PLACED STEEL FENCE POST WITH _____

DOUGLAS CO. SURVEYOR'S OFF.

Agency

SURVEY MARKER SIGN _____

GARY L. LANGLITZ

Party Chief

ATTACHED ONE FOOT NORTH _____

Gary L. Langlitz

Notekeeper

OF THE CORNER. _____

LARRY E. MONREAN

Witnesses

PETER L. EARLE

OK
[Signature]