

DATE: 12-8-77

T 29 S

S $\frac{1}{16}$

R 6 W

25

| 30

R 5 W

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s M 37-20

Monument(s) Found: (Condition and Source) A 1" I. PIPE, FIRMLY SET EXTENDING 14" ABOVE GROUND, WITH BRASS CAP ATTACHED, MARKED!

COUNTY SURVEYOR'S OFFICE

T 29 S

S $\frac{1}{16}$

R

6 25

| 30

R

W

W

1969

Accessories Found: (Condition and Source) FROM WHICH THE COUNTY SURVEYOR'S 1969 BT'S BEAR AS FOLLOWS:

A 9" NOW 11" D. FIR, ALIVE WITH WELL-HEALED DOUBLE BLAZE

BEARS S 83° E 36² FT.

AND AN 11" NOW 12" D. FIR, ALIVE WITH WELL-HEALED DOUBLE BLAZE,

BEARS N 43° W 10² FT. (REC. PER 1969 SURVEY N 43° W 11² FT.)

237 T 29-6 X

185 T 29-5 X

C.S. No. 59/42-23 Page 1 of 1

C

(SEE M 37-20)

RECENT

THIS 1969 CORNER LOCATION IS NOW WRONG DUE TO THE IDENTIFICATION OF THE
 COMMON ORIGINAL CORNER TO SECTIONS 19 AND 30, T29S R5W, AND SECTIONS 24 AND 25,
 T29S, R6W. WE THEREFORE RESET THIS CORNER BY SURVEY AT ITS PROPER
 PROPORTIONATE LOCATION AS FOLLOWS:

RENEWAL

Monument Set: (Procedure and Description) WE REMOVE THE 1969
 MONUMENT AND SET IT AT THE TRUE CORNER POINT, EXTENDING 6" ABOVE GROUND
 WE ADD THE MARKINGS "RESET 1977" TO THE BRASS CAP.

AT THE 1969 CORNER LOCATION, WE SET A $\frac{5}{8}$ " x 30" I. ROD, WITH ALUMINUM CAP
 ATTACHED, MARKED: "DOUGLAS CO. SURVEYOR 1977"

New Accessories: (Description) THE 1969 BEARING TREES ARE NOW
 LOCATED AS FOLLOWS:

AN 11" D. FIR BEARS CONDITION NOTED ABOVE BEARS S 87° E 40⁷ FT.
 AND A 12" D. FIR, CONDITION NOTED ABOVE BEARS N 21¹/₂° W 9⁷ FT.
 A $\frac{5}{8}$ " IRON ROD WITH ALUMINUM CAP ATTACHED, MARKED AS NOTED ABOVE,
 BEARS N 73° E 3⁸ FT.

Location and Comments:

A N-S FENCE BEARS
 EAST APPROX. 13⁵ FT.

20° EAST
DOUGLAS COUNTY SURVEYORS OFF.
GARY L. LANGLITZ
Gary L. Langlitz
PETER L. EARLE
FRANK SILAGY

Compass Declination
 Agency
 Party Chief
 Notekeeper
 Witnesses

OK
