

T295

N 1/16

R 6 S25 | S30 R 5  
W W

DATE: 12-12-77

Condition Report On  
Not Found  
Renewed  
Unrecorded  
 Surveyed In  
Referenced Out

Previous Renewal #'s M 37-20

Monument(s) Found: (Condition and Source) A 1" x 36" IRON PIPE  
WITH BRASS CAP SET 13" ABOVE GROUND, MARKED  
"COUNTY SURVEYORS OFFICE"  
T295

R N 1/16 R  
6 S25 | S30 5  
W W  
1969

I REMOVE AND RESET TO PROPORTIONED POINT  
BETWEEN NE AND SE SECTION CORNER, SECTION 25.  
CORNER WAS ORIGINALLY PROPORTIONED BETWEEN THE NW COR.  
S19 AND S.W. COR. S30, NEEDS RESURVEYED SINCE THE S.W. COR. S19  
WAS FOUND.

(FROM NEW LOCATION)

Accessories Found: (Condition and Source) A 24" NOW 26" ASH,  
MEASURED BELOW THE FORK, BEARS N18°E 59<sup>2</sup> FT (REC,  
N6°E 52<sup>5</sup> FT. WITH VISABLE SCRIBING "N 1/16 CS BT" IN  
PARTIALLY HEALED DOUBLE BLAZE, A 16" CEDAR BEARS  
N61°E 65<sup>5</sup> FT. WITH VISABLE SCRIBING "CS B" IN PARTIALLY  
HEALED PARTIALLY HEALED SINGLE BLAZE.

#243 T29-6 X

#191 T29-5 X

RENEWAL

Monument Set: (Procedure and Description) RESET BRASS CAP,  
8" ABOVE GROUND IN A 15" DIA. MOUND OF STONE,  
AT PROPORTIONED LOCATION, STAMPED "RESET 1977" ABOVE "1969".  
IN A 15" DIA. MOUND OF STONE

I SET A 5/8" x 30" IRON ROD WITH ALUMINUM CAP STAMPED

"DOUGLAS CO." AT OLD LOCATION OF BRASS CAP, 1 1/2" DIA. ALUM.  
1977  
SURVEYOR CAP BEARS N70°26'E 13<sup>05</sup> FT.

New Accessories: (Description) NONE

Location and Comments:  
CORNER IS 08 FT NORTH  
OF EAST-WEST FENCE.  
CORNER OF FENCE TO  
SOUTH AND WEST BEARS  
S87°E 25 1/2 FT.

<u>20°E</u>	Compass Declination
<u>DCSO</u>	Agency
<u>R.B. KIMBERLING</u>	Party Chief
<u>R.B. Kimberling</u>	Notekeeper
<u>F.C. SILAGY</u>	Witnesses

OK  
*[Signature]*