

T215 R11W

DATE: 4-25-78

C-N 1/16  
S. 5

Condition Report Onl  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) NONE

# 112 ✓

RENEWAL

Monument Set: (Procedure and Description) CORNER LOCATION

DETERMINED BY SURVEY. AT THE CORNER POINT, WE SET A 1" X 30" IRON PIPE, 28" IN THE GROUND, WITH BRASS CAP ATTACHED, MARKED:

DOUGLAS COUNTY SURVEYOR

T 21 S

C

N 1/4 S 5

C

R 11 W

1978

New Accessories: (Description) \_\_\_\_\_

WE MARK NEW BT'S AS FOLLOWS:

A 21" D. FIR, SCRIBED "CN 1/4 S 5 CS BT" ON A DOUBLE BLAZE,  
BEARS N 77° W 66 1/2 FT.

AND A 24" D. FIR, SCRIBED "CN 1/4 S 5 CS BT" ON A DOUBLE BLAZE,  
BEARS N 54° E 91 1/2 FT.

Location and Comments:

20° EAST

Compass Declination

CORNER LOCATED APPROX.  
30 FT. WEST OF SMALL  
CREEK, COURSE S 50° W.

DOUGLAS Co. SURVEYOR'S OFF

Agency

GARY L. LANGLITZ

Party Chief

Gary J. Langlit

Notekeeper

FRANK C. SILAGY

Witnesses

OK  
shl