

T235 R6W

S 1/16

56 | 55

DATE: 3-2-78

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) A 1" T IRON WITH 1" DIA.

BRASS CAP SET 3" ABOVE GROUND, MARKED
"WILFORD N. HAINES"
239
SURVEY POINT
DRAIN, ORE.

WITH HAINES' WASHER

Accessories Found: (Condition and Source) A 9" DIA. FIR^N IS DOWN,

BROKEN STUMP BEARS N44°W 12¹/₂ FT. WITH SCRIBING "1/16 56

BT" ON SINGLE BLAZE. A 7" DIA. FIR IS DOWN, BROKEN

STUMP BEARS S69°E 2³/₄ FT. WITH SCRIBING "1/16 5 BT IN

SINGLE BLAZE.

#73-X

C

RENEWAL

Monument Set: (Procedure and Description) A 1" IRON PIPE WITH
BRASS CAP SET 6" ABOVE GROUND AND MARKED
"DOUGLAS COUNTY SURVEYOR"
T235 R6W

S 1/16
56 | 55
1978

I PLACE HAINES' T IRON AND BRASS CAP UNDER NORTH LIP
OF DOUGLAS COUNTY SURVEYOR BRASS CAP.

New Accessories: (Description) A 10" DIA. W. FIR BEARS
N34°W 92²-FT., I DOUBLE BLAZE AND MARK "S 1/16 S6 CS BT".
A 6" DIA. W. FIR BEARS N55°E 26³-FT., I DOUBLE BLAZE
AND MARK "S 1/16 S5 CS BT".

Location and Comments:
CORNER IS AT EAST
EDGE OF CLEARCUT
UNIT, AT TOP OF
STEEP CLIMB 1/4 MI.
NORTH OF BRUSH CR. RD.

20°E
DCSO
R.B. KIMBERLING
R.B. Kimberling
P.L. EARLE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK *[Signature]*