

DATE: 3-14-78

T245 R2W

S21 | S22

S28 | S27

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) A 3" SQUARED WOODEN POST, NOT ORIGINAL.

Accessories Found: (Condition and Source) A 24" NOW 41" DIA. HEMLOCK STUMP BEARS N39°E (REC. N84°E) 40[±] FT. WITH A WELL HEALED BLAZE. A 24" NOW 30" DIA. CEDAR BEARS S20°E 14[±] FT. (REC 16[±] FT.) WITH SCRIBING "2W 2" IN A PARTLY HEALED SINGLE BLAZE. A 5" NOW 16" DIA. CEDAR BEARS S68 1/2°W (REC. S66°30'W) 20[±] FT. WITH AN ALMOST HEALED SINGLE BLAZE. A 60" NOW 63" DIA. FIR STUMP BEARS N35°W 21[±] FT. WITH A WELL HEALED SINGLE BLAZE.

#96 ✓

C.S. 59/46-75

C

RENEWAL

Monument Set: (Procedure and Description) A 1" x 36" IRON PIPE

WITH A BRASS CAP SET 6" ABOVE GROUND, MARKED
"DOUGLAS COUNTY SURVEYOR"
T24S R2W
S21 | S22
S28 | S27

New Accessories: (Description) A 11" DIA. HEMLOCK BEARS N84 1/2° E

40⁹ FT., I DOUBLE BLAZE AND MARK "T24S R2W S22 CS BT"

A 6" DIA. HEMLOCK BEARS N14° W 98⁹ FT., I DOUBLE BLAZE
AND MARK "T24S R2W S21 CS BT"

Location and Comments:

<u>20° E</u>	Compass Declination
<u>DC50</u>	Agency
<u>R. B. KIMBERLING</u>	Party Chief
<u>R. B. Kimberling</u>	Notekeeper
<u>P. L. EARLE</u>	Witnesses
<u>F. C. SILAGY</u>	

OK
[Signature]

SW COR

Section 22 Twp 24 S Rge 2 W

Date: 4/14/77



How was corner identified? Orig Bts.

Condition of corner: Fair

Best route to reach corner: _____

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size	40" DF Stump	60" DF Stump	28" Ced	12 Ced
Dist. & Bearing	41 1/2 N 40 E	19 1/2 N 30 W	12 1/2 S 26 E	18 1/2 S 66 W
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.	Stump	Stump.		
Tags, Marks, etc.	Wegh Tags	—		

H.W. Johnstone
 Signed
 C. S. File No. 59/40