

T245 R5W

DATE: 3-13-78

S10	S11
S15	S14

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #49

Monument(s) Found: (Condition and Source) A 1" x 36" IRON PIPE SET 22"

IN GROUND, BENT OVER, WITH A BRASS CAP MARKED...

COUNTY SURVEYORS OFFICE"

T245 R5W

S10	S11
S15	S14

1960

Accessories Found: (Condition and Source) (O.B.T.'S) A 20" NOW 60" DIA.

BLACK OAK (REC. Y. OAK) BEARS S44°E (REC. S47°E) 63¹/₄ FT WITH

WELL HEALED SCARS. A 20" NOW 36" DIA, OAK IS DOWN (ON BLAZE AREA)

APPROX. BEARS S74°W 124¹/₂ FT. A 24" NOW 32" DIA, BURNED OUT OAK

SNAG BEARS N51¹/₂°E (REC. N50°E) 232³/₄ FT., WITH REVERSE

SCRIBING "4" IN A HEALED BLAZE.

(REN. #49) A 18" NOW 24" DIA, D. FIR (R. FIR) BEARS S29°E 18²/₄ FT.

#103A

C

WITH A WELL HEALED DOUBLE BLAZE, A 12" NOW 13" DIA.

MADRONE (LAUREL), MEASURED BELOW THE FORK, BEARS 517°W

19¹ FT. WITH A WELL HEALED DOUBLE BLAZE, A 6" NOW 11" DIA.

D. FIR (R. FIR) BEARS N 45° W 222 FT. WITH A WELL HEALED
DOUBLE BLAZE. A 17" NOW 23" DIA. D. FIR (R. FIR) BEARS N 79° E
399 FT. WITH A WELL HEALED DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) I STRAIGHTEN THE
BENT IRON PIPE AND RESET IN ORIGINAL LOCATION,
STAMP "RESET 1978" ABOVE EXISTING DATE "1960".
BRASS CAP IS 3" ABOVE GROUND.

New Accessories: (Description) NONE

Location and Comments:		Compass Declination
CORNER IS ON NORTH	<u>20°E</u>	Agency
EDGE OF A JEEP TRAIL	<u>DCSO</u>	Party Chief
202 FT. NORTH OF AN	<u>R. B. KIMBERLING</u>	Notekeeper
EAST-WEST FENCE.	<u>R. B. Kimberling</u>	Witnesses
	<u>P. L. EARLE</u>	

OK
[Signature]